







Conductor Testing	477	795	1272	596TW	675TW	774(46/37)
Tensile Strength	1	√	V	V	√	V
Stress-Strain Curves	V	V	V	V	V	V
RT Creep	\checkmark	√	V	n/a	n/a	
ET Creep	\checkmark	n/a	n/a	n/a	n/a	
Impact	\checkmark	\checkmark	n/a	n/a	n/a	
Crush	\checkmark	√	n/a	n/a	n/a	
Torsion	\checkmark	√	n/a	n/a	n/a	√
CTE	\checkmark	\checkmark	n/a	n/a	n/a	
Core strain $f(T,S)$	\checkmark	n/a	n/a	n/a	n/a	
DC Resistance	\checkmark	\checkmark	V	V		V
Fault Current	$\sqrt{}$	V	n/a	V	n/a	active
Lightning Strike	1	V	n/a	n/a	n/a	
Aeolian Vibration	\checkmark	\checkmark	V	V	n/a	2005
Sag	\checkmark	\checkmark	active	V	V	2005
Corrosion	n/a	\checkmark	n/a	n/a	n/a	n/a
_© Sheave	active	V	active	active		active
Post-field test	1	2005	2005		V	


Accessory Testing	477	795	1272	596TW	675TW	774
Alcoa						46/37
DE Strength	V	V	V	V	V	V
Joint Strength	1	j	1	j	à	2005
RT Sustained Load DE + Joint	1	Ž	a)	Ž	N.	2005
ET Sustained Load DE + Joint	1	N.	N.	N.	N N	2005
Current Cycle	N	1	V	V	v n/a	2005
Dampers	N N	N A	٨	N A	n/a n/a	4
Repair Sleeve	N al	V 4:	۷	٧	n/a	V
PLP	٧	active	active			
DE Strength	ما	J	J	n/a	J	active
Joint Strength	J	J	J	11/α	J	active
RT Sustained Load DE + Joint	J	J	1		active	2005
ET Sustained Load DE + Joint	J	J	J		active	2003
Current Cycle	active	J	•		•	
Suspension - turn angle	active	j	n/a	n/a	n/a	2005
Suspension - unbalanced load	J	J	11/a	11/a	n/a	2005
Suspension - ET profile	J	J	J	J	n/a	2005
Galloping	J	J	J	J	n/a	2005
Aeolian Vibration	J	J	J	J	n/a	2005
Corona RIV	J	J	•	Y	11/ a	2003
Spacer	•	active				
© M. M. Splice	٦	1			active	
Post –field hi-temp	Ž	2005	2005		delive	


High Temperature Testing

(210°C-continuous, 240°C-emergency)


Conductor Accessories Core Al-Zr thermal expand current cycle strength aging fault current thermal profile aging resistance sustained load creep sag thermal cycles thermal cycle thermal cycles sustained current sustained current thermal expand


© 3M 2005


















Thermal Upgrade Application Guide

Competitive Performance: **AVOIDING REBUILDS**

Replacement ACCR	Ampacity ACCR	Capacity Increase (x times ACSR)		Equiv. ACSR Line
kcmil	amps	min	max	kcmils
336	937	1.6	3.1	636
397	1,046	1.6	3.1	795
477	1,179	1.6	3.1	1,033
795	1,653	1.6	3.3	1,590
1033	1,940	1.7	3.4	2 X 636
1272	2,229	1.7	3.5	2 X 954
1590	2,586	1.7	3.5	2 X 1113



Xcel Installation


(Completed in 11 months)


- Plant expansion was \$100M investment
- Wetlands
- Challenging timelines











Simpler and Faster Than Rebuilding (Eight week installation)



No bucket truck access





ATV access only

© 3M 2005

Lake Crossing

Increased Capacity Without Environmental Impact or Visual Change to the Line

Energized June, 2005 (10 circuit miles)

Before

- Significant increase in current capacity
- Met schedule
- Preserved sensitive wetland environment
- No disturbance to residential areas
- Cost effective



© 3M 2005

After Installing 3M ACCR

